ibd G02 [F03]

#I002 : Functioning mode

#I004 : Physical value 2

#[SingleBlock_F03] : Function 3

Description

convert a physical signal into electronical data with saturation above MaxValue and below MinValue

Requirements :

Output I014 encodes in electronical data the I001 physical signal with a precision of x% [R1]

#I005 : Measure 2

Block diagram representing the function with input and output flows