



 A product has to be assembled in good conditions to enable mass production. The block diagram gives an example of assembly needs. External elements are represented in lateral boxes and corresponding needs are displayed in text above lines between the central box and lateral boxes. Hypertext links point to requirements.