

#I002 : Functioning mode

#I004 : Physical value 2

#UNKNOWN :???

#I014 : Signal 2

Requirements

Time without relevant signal 2 at
switch on shall be less than xms
[R001]

Code

During Xms I014 := \$FF



Block diagram representing the function with input and output flows