

#I002 : Functioning mode

#I004 : Physical value 2

#[SingleBlock_F03] :
Measure Physical Value

#I005 : Measure 2

Description

convert a physical signal into electronic data with saturation above MaxValue and below MinValue

Requirements :

Output I014 encodes in electronic data the I001 physical signal with a precision of x% [R1]



Block diagram representing the function with input and output flows