

#I010 : Actuation signal 2

#[SingleBlock_F09] : Realize Actuation 2

#I012 : Physical action 2

Description

realise physical action

Requirements :

I010 shall be transformed into physical action I012 in less than x seconds [R001]

I010 shall be transformed into physical action I012 with a precision better than c %. [R002]



Block diagram representing the function with input and output flows